All,

Please see the changes from the walkthrough today at Gailcrest.

The Hendricks County Surveyor's Office is looking to get quotes for a project in the Gailcrest Subdivision. I have included an aerial and below a scope of work.

- 1. Dredge 230ft of ditch flowline starting at the road culvert heading east to the bend in the ditch. All spoils will need to be hauled away.
- 2. On the south ditch bank on the east side of Kaymar Dr, Place 120ft of geotextile fabric and reventment rip rap from the ditch flowline to the top of the bank.
- 3. At the bend on the south bank of the ditch use some of the spoils in that area to fix the ditch bank and seed and straw mat that area.
- 4. On west side of Kaymar Dr, pull back 15ft long of the north and south ditch bank from the ditch flowline to the top of the bank.
- 5. Place geotextile fabric and revetment rip rap on the same 15ft of north and south ditch bank on the west side of the culvert.
- 6. Once the job is completed, finish grade all the disturbed work areas with grass seed and straw.

I will be doing a walkthrough on 8/13/25 at 1pm. Please let me know if you will be attending. I Would like to have quotes returned to me by 4pm on 8/25/2025 to be opened at the 8/26/2025 Drainage Board. This project will have a 30-day completion date from the time the approved quote is awarded. We will meet at 227 Kaymar Dr. Danville. Please let me know if you have any questions.

